Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
<u>.</u>	461	(60/324,292).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/12/02 07:58
L2	5312	(123/90.11,90.12,90.15,90.16,90. 17).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/12/02 07:59
L3	5	1 and 2	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/12/02 07:59
L7	6441	valve with overlap	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/12/02 09:22
L8	3	7 with (exhaust adj throttle)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/12/02 09:22
S65	5	("6199527").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/12/02 07:58
S66	2	JP-08210123-\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:51
S67	276	exhaust adj throttle adj valve	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:31
S68	3	S67 with failure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:28
S69	10032	intake with pressure with sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	ÓR	ON	2004/11/15 11:28
S70	1266	intake adj pressure adj sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:31
S71	0	S67 with S70	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:28

S72	0	S67 same S70	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:28
S73	5	S67 and S70	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:28
S74	413	exhaust adj throttle	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:31
S75	0	S70 same S74	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:31
S76	245	exhaust adj pressure adj sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:31
S77	1	S67 same S76	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:32
S78	12163	exhaust with emission with control	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:33
S79		S67 and S78	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:33
S80	4	S79 and S70 ·	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:46
S81	6413	exhaust adj pressure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:47
S82	26	S70 with S81	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:48
S83	5	S82 and failure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:52

S84	5864	intake adj pressure	US-PGPUB;	OR	ON	2004/11/15 11:52
			USPAT; EPO; JPO; DERWENT			
S85	11787	exhaust with throttle	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:54
S86	160	S84 with S85	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:53
S87	64	S86 with (fail\$3 detect\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:53
S88	1941	exhaust near2 throttle	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:54
S89	3	S88 with (fail\$3 detect\$3) with S84	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:56
S90	276	exhaust adj throttle adj valve	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:17
S91	44	S90 with (failure fault detect\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:57
S92	1	S91 with (intake with pressure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 11:58
S93	8	S91 with (intake)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:02
S94	23974	intake near2 pressure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:02
S95	470	S94 with (exhaust adj pressure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:03

S96	1747	(123/90.15).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/11/15 12:04
S97	5	S95 and S96	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:06
S98	3	S95 with fail\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:42
S99	5	S67 with (fail\$3 malfunction fault\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:45
S10 0	6413	exhaust adj pressure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:45
S10 1	217	S100 with (intake adj pressure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:48
S10 2	31146	emission with exhaust	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 12:49
S10 3	51	S101 and S102	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 13:02
S10 4	0	S67 with diagnosis	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/15 13:02
S10 5	6231	exhaust adj emission adj control	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 15:46
S10 6	4515	S105.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 15:46
S10 7	52	S106 and (intake near2 pressure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:00

S10 8	32	S106 and (exhaust with (intake near2 pressure))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:01
S10 9	278	exhaust adj throttle adj valve	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:17
S11 0	2	S109 with detect\$3 with fail\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:24
S11 1	4	S109 with fail\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:25
S11 2	2	S109 with malfunct\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR .	ON	2004/11/18 16:27
S11 3	1397266	exhaust adj pressure sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:27
S11 4	246	exhaust adj pressure adj sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:27
S11 5	0	S109 with S114	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:27
S11 6	1	S109 same S114	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:30
S11 7	741	exhaust with fail\$5 with pressure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:31
S11 8	378	S117 with valve	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:31
S11 9	60	S118 with intake	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/18 16:31

S12 1	2	JP-08210123-\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:18
S12 2	233	exhaust with valve with failure with pressure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:19
S12 3	8	("5732552" "5767386" "5974787" "6082176" "6138453" "6233927" "6381952" "6477830").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2004/11/30 08:49
S12 4	8	("5732552" "5767386" "5974787" "6082176" "6138453" "6233927" "6381952" "6477830").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2004/11/30 08:52
S12 5	200	intake adj sensor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:56
S12 6	419	exhaust adj throttle	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:56
S13 0	0	S125 and S126	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:57
S13 1	0	60/277,276,285,292,284,286,324	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:58
S13 2	4052	(60/277,276,285,292,284,286, 324).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/11/30 08:58
S13 3	24056	intake near2 pressure	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:59
S13 4	56968	exhaust near2 valve	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:59
S13 5	642	S133 with S134	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 08:59

S13 6	18	S132 and S135	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 09:12
S13 7	12	S126 with (fault\$3 fail\$3 diagnos\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 09:43
S13 8	741	("73,118.1").PN. or (701/108, 114).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/11/30 09:43
S14 0	4758	S132 S138	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 09:44
S14 1	3117	(123/90.15,90.17).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/11/30 09:44
S14 2	40	S140 and S141	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 09:47
S14 3	. 68	(fail\$4 diagnos\$5 falt\$3) with overlap\$3 with valve	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 09:49
S14 6	39	(fail\$4 diagnos\$5 falt\$3) with overlap\$3 with valve with exhaust	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 09:49
S14 7	29	S146 and S141	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 09;53
S14 8	0	S126 with valve with closing with overlap	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON.	2004/11/30 09:54
S14 9	4	S126 and S141	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/30 10:04
S15 0	1758	(123/90.15).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2004/11/30 10:04